## ABSTRACT

## USE OF SURFACE MEASURING PROBES

5 A method of measuring an artefact 5 using a machine 2 on which a measuring probe 6 is mounted. The probe is brought into contact with the artefact and movement continued for a limited distance to deflect the stylus 7. The machine and probe outputs are recorded whilst the probe is free and when the stylus is deflected. A 10 model of the probe and CMM outputs during both contact and non-contact between the probe and artefact is fitted to the data to allow the contact position when the stylus contacts the artefact with zero force to be 15 determined. The probe outputs may be fitted to the model individually to determine a single contact position. By using data during movement of the probe towards and away from the artefact, errors due to time delays may be corrected.

20

Fig 3